



Quadex, Inc.

4801 Crystal Hill Rd.
North Little Rock, AR 72118
Phone: (501) 758-8628
Toll Free: (888) 831-1650
Fax: (501) 758-3814

MATERIAL SAFETY DATA SHEET

PRODUCT: QUADEX HYPERFORM

HAZARDOUS INGREDIENTS/ IDENTITY INFORMATION		PHYSICAL/CHEMICAL CHARACTERISTICS	
Common Names	ACGIH TLV	Boiling Point: NA	Specific Gravity: NA
Portland Cement	10 mg/M ³	Vapor Pressure: NA	Melting Point: NA
Admixtures	10 mg/M ³	Vapor Density: NA	Evaporation Rate: NA
FIRE AND EXPLOSION HAZARD DATA		Solubility in Water: Slight; 0.1% - 1.0%	
Flash Point: NA		Appearance and Odor: Grey and Odorless	
Special Fire Fighting Procedures: Non-Combustible Material		REACTIVITY DATA	
Extinguishing Media: NA		Stability: Stable	
Usual Fire and Explosion Hazards: None		Conditions to Avoid: Although no hazardous reaction will occur; product should be kept dry.	
		Hazardous Decomposition or Byproducts: None	
		Hazardous Polymerization: Will not occur	
HEALTH HAZARD DATA			
Routes of Entry:	Inhalation: Yes	Skin: Yes	Ingestion: Yes
Carcinogenicity:	NTP: No	IARC Monographs: No	OSHA Regulated: No
Signs and Symptoms of Exposure: Dust could cause inflammation of eyes and upper respiratory system. Wet cement can dry or cause alkali burns to skin.			
Medical Conditions Generally Aggravated by Exposure: May aggravate existing eye, lung, and nose conditions.			
Emergency and First Aid Procedures: <i>Inhalation:</i> Remove to fresh air. Administer oxygen if necessary. <i>Skin Contact:</i> Rinse with soap and water. <i>Eye Contact:</i> Flush with large amounts of water.			
PRECAUTIONS FOR SAFE HANDLING AND USE			
Steps to Be Taken in Case Material is Released or Spilled: Dispose into labeled waste container for reuse or disposal. Wear adequate protective clothing and equipment. Wash area down with water.			
Waste Disposal Method: Dispose in sanitary landfill in accordance with federal, state and local regulations.			
Precautions to be Taken in Handling and Storing: Store in dry place and keep containers sealed.			
Other Precautions: None			
CONTROL MEASURES			
Respiratory Protection: Not normally required. Use NIOSH/MESHA approved respirator when needed.			
Ventilation: Local exhaust recommended if necessary. Mechanical recommended if necessary.			
Protective Gloves: Rubber		Eye Protection: Goggles	
Other Protective Clothing or Equipment: Standard work clothing and shoes.			
Work/Hygienic Practices: NA			